








# FELICE






Teil	Pcs	Colli	Teil	Pcs	Colli
1	1x	1/6	4	1x	4/6
2.1	1x	2/6	5	1x	5/6
2.2	1x	2/6	6	2x	6/6
3	1x	3/6	7	1x	1/6









A	B	C	D	E	F	G	H
4x	18x	2x		4x	38x	2x	2x
H-150	3,5x35	H-150	$\varnothing$ 20		4x16	3,5x70	H-165
I	J	K	L	M	N	O	
4x	4x	14x	14x	1x	1x	5x	
				H-120	H-150	$\varnothing$ 30	









1




A	B	D	E	F	N	O
						
4x	14x	4x	1x	10x	1x	1x
H-150	3,5x35	$\varnothing 20$		4x16	H-150	$\varnothing 30$

3




B	H	I	J	O	6
					
4x	2x	4x	4x	2x	2x
3,5x35	H-165			$\varnothing 30$	


4




5




6



7




8




F		K		L	
	28x		14x		14x
4x16					

9




G		M
2x		
3,5x70		H-120

10



11



12

