
































MUNTRIOL




PARTS LIST:




A-1PC 	B-1PC 	C-2PCS 
D-2PCS 	E-1PC 	F-2PCS 
G-1PC 	H-1PC 	I-1PC 
J-2PCS 	K-1PC 	L-2PCS 
M-2PCS 	N-1PC 	O-32PCS 
P-32PCS 	Q-16PCS 	R-2PCS 
S-2PCS 	T-1PC 	

HARDWARE LIST:


1 -1PC 	2 -24PCS 	3 -16PCS 
4 -12PCS 	5 -61PCS 	6 -61PCS 
7 -8PCS 	8 -1PC 	9 -4PCS 
10 -9PCS 		




step 4




step 6





step 5





step 7





step 8



step 10



step 9



step 11

