




NINA B 180




- 1** G40
- 2** G60o
- 3** G80W
- 4** D40S1
- 5** DP601D
- 6** D80Z
- 7** Worktop 180

NINA B G40








1x 4mm z1	8x Ø 6,3x50mm e27	8x Ø 12mm s3
8x Ø 8x30mm f1	2x Ø 35mm ab1	8x Ø 5mm d1
2x n165	1x L=128/148mm c252	5x 10x10x15mm i2
3x Ø 4,2x16mm p21	4x Ø 3,5x16mm p51	2x Ø 4x25mm p26
2x 80x27x5mm j1	4x Ø 4x30 mm p30	2x M4 r3

A	B (mm)		C	D
1	716	280	16	x1
2	716	280	16	x1
3	368	266	16	x1
4	368	280	16	x1
5	706	384	2.5	x1
6	367	250	16	x2
7	396	713	16	x1









1	n165 x 2 	p30 x 4 Ø 4x30mm	d1 x 8 Ø 5mm	b1 x 2 40x50x12mm	f1 x 8 Ø 8x30mm
----------	--------------	-------------------------	---------------------	--------------------------	------------------------






6

j1 x 2
80x27x5mm





NINA B 180





- 1** G40
- 2** G60o
- 3** G80W
- 4** D40S1
- 5** DP601D
- 6** D80Z
- 7** Worktop 180






NINA B G60o



1x 4mm z1	8x Ø 6,3x50mm e27	8x Ø 12mm s3
8x Ø 8x30mm f1	2x Ø 35mm ab1	2x x4 m5
2x n165	1x L=128/148mm c252	4x 10x10x15mm l2
4x Ø 4,2x16mm p21	4x Ø 3,5x16mm p51	2x Ø 4x25mm p26
2x 80x27x5mm j1	4x Ø 4x30 mm p30	2x M4 r3







A	B (mm)			C	D
1	358	280	16	x1	1/1
2	358	280	16	x1	1/1
3	568	266	16	x1	1/1
4	568	280	16	x1	1/1
5	582	348	2.5	x1	1/1
6	596	355	16	x1	1/1





7

j1 x 2
80x27x5mm





NINA B 180





- 1** G40
- 2** G60o
- 3** G80W
- 4** D40S1
- 5** DP601D
- 6** D80Z
- 7** Worktop 180




NINA B G80W



1x 4mm z1	12x Ø 6,3x50mm e27	12x Ø 12mm s3
12x Ø 8x30mm f1	2x Ø 35mm ab1	4x m5
2x n165	2x L=128/148mm c252	7x 10x10x15mm l2
16x Ø 4,2x16mm p21	8x Ø 3,5x16mm p51	4x Ø 4x25mm p26
2x 80x27x5mm j1	4x Ø 4x30 mm p30	2x M4 r3
		8x 10x6x10mm d6
		2x Ø 35mm ab2







A	B (mm)		C	D
1	716	280	16	x1 3/8
2	716	280	16	x1 3/8
3	768	266	16	x1 3/8
4	768	266	16	x1 3/8
5	768	280	16	x1 3/8
6	782	704	2,5	x1 3/8
7	796	355	16	x1 7/8
8	796	140	16	x1 7/8
9	764	192	4	x1 7/8
10	796	83	16	x1 7/8





7

j1 x 2
80x27x5mm







NINA B 180



- 1** G40
- 2** G60o
- 3** G80W
- 4** D40S1
- 5** DP601D
- 6** D80Z
- 7** Worktop 180



NINA B D40S1




1x 4mm z1	8x Ø 6,3x50mm e27	8x Ø 12mm s3
8x Ø 8x30mm f1	2x Ø 35mm ab1	2x M4 r3
32x Ø 3x16mm p50	2x L=128/148mm c252	4x Ø 4x25mm p26
3x Ø 4,2x16mm p21	4x Ø 3,5x16mm p51	5x 10x10x15mm l2
4x Ø 4x30 mm p30	4x h=100mm k52	2x k61
	1x L=450mm n6	4x Ø 6x13mm e1




A	B (mm)		C	D
1	704	500	16	x1 4/8
2	704	500	16	x1 4/8
3	400	500	16	x1 4/8
4	367	80	16	x1 4/8
5	367	80	16	x1 4/8
6	382	710	2.5	x1 4/8
7	400	100	16	x1 4/8
8	366	470	16	x1 4/8
9	448	336	16	x1 4/8
10	336	71	16	x1 4/8
11	396	140	16	x1 7/8
12	396	570	16	x1 7/8






7




8




9

a1 x 2	p51 x 4	c252 x 1	p26 x 2
Ø 35mm	Ø 3,5x16mm	L=128/148mm	Ø 4x25mm





10



R

L





NINA B 180




- 1** G40
- 2** G60o
- 3** G80W
- 4** D40S1
- 5** DP601D
- 6** D80Z
- 7** Worktop 180

NINA B DP601D










1x 4mm z1	8x Ø 6,3x50mm e27	8x Ø 12mm s3
8x Ø 8x30mm f1	2x Ø 35mm ab1	2x M4 r3
16x Ø 3x16mm p50	4x h=100mm k52	4x L=75x25x15mm n14/2
18x Ø 4,2x16mm p21	4x Ø 3,5x16mm p51	2x k61

A	B (mm)		C	D
1	704	500	16	x1 5/8
2	704	500	16	x1 5/8
3	567	500	16	x1 5/8
4	600	500	16	x1 5/8
5	596	124	2.5	x1 5/8
6	600	100	16	x1 5/8
7	596	116	16	x1 7/8




1	b1 x 4 40x50x12mm	f1 x 8 Ø 8x30mm	k62 x 2 	p50 x 4 Ø 3x16mm
----------	--------------------------	------------------------	-------------	-------------------------







NINA B 180




- 1** G40
- 2** G60o
- 3** G80W
- 4** D40S1
- 5** DP601D
- 6** D80Z
- 7** Worktop 180

NINA B D80Z










1x 4mm z1	8x Ø 6,3x50mm e27	8x Ø 12mm s3
8x Ø 8x30mm f1	4x Ø 35mm ab1	2x M4 r3
20x Ø 3x16mm p50	2x L=128/148mm c252	4x Ø 4x25mm p26
12x Ø 4,2x16mm p21	8x Ø 3,5x16mm p51	2x k61
2x Ø 4x30 mm p30	4x h=100mm k52	4x L=75x25x15mm n14/2

A	B (mm)		C	D
1	704	500	16	x1 6/8
2	704	500	16	x1 6/8
3	767	80	16	x1 6/8
4	767	80	16	x1 6/8
5	800	500	16	x1 6/8
6	200	200	2,5	x1 6/8
7	800	100	16	x1 6/8
8	796	140	16	x1 6/8
9	396	570	16	x2 7/8




1	b1 x 4 40x50x12mm	f1 x 8 Ø 8x30mm	k62 x 2 	p50 x 4 Ø 3x16mm
----------	--------------------------	------------------------	-------------	-------------------------








NINA B 180



- 1** G40
- 2** G60o
- 3** G80W
- 4** D40S1
- 5** DP601D
- 6** D80Z
- 7** Worktop 180

NINA A Worktop 180



4x		8x	
Ø 4x30 mm	p30	Ø 4,2x16mm	p21

A	B (mm)			C	D
1	1800	600	28	x1	8/8

1	p30 x 4  Ø 4x30mm	p21 x 8  Ø 4,2x16mm
----------	--	--

