






























- G  x10
M6x16
- H  x16
M6x30
- I  x8
M6
- J  x1
4 mm
- T14  x2
Fi4x50
- T13  x2
Fi6x50
- J11  x2
- P13  x4
Fi4x16






Číslo	Rozměry/Rozmery			Ks	Balíky
1(A)	700	380	45	1	1
2(B)	180	380	45	2	1
3(C)	1060	336	25	2	1
4(D)	920	380	50	1	1
5(E)	920	380	50	1	1
6(F)	700	20	20	1	1
















- P13  x4
Fi3,5x13
- J11  x2
- T14  x2
Fi4x50
- T13  x2
Fi6x50



- (J11)  x2
- (P13)  3,5x13 x4
- (T13)  6x50 mm x2
- (T14)  4x50 mm x2

-  2
-  3
-  4
-  5
-  6

