








Sc 314




Montážní/Montážny návod



COLLI 1/2				
B	347	x	378	6




COLLI 2/2				
A	1000	x	380	1
C	1000	x	380	2
D	1000	x	380	1






1x 0013K	24x 0001K
24x 0092K	24x 0054K
24x 0019K	4x 0149K
1x 0109K	4x16 1x 0006V
ø8 1x 0051K	5x50 1x 0013V








1)



2)







3)






4)



2x





5)







6)



7)



8)

 1x 0109K	 4x16 1x 0006V	 5x50 1x 0013V	 ø8 1x 0051K
---	---	---	---

var.1

var.2

