







# SPARTIA



1


2

3



ZC7521AR

1	1x
2	4x
3	1x




1/1

A M6X10



8x

B M6X20




4x

C Ø18xØ6x1.5



8x


D 5MM



1x


I.

1



A	M6x10
	4x
D	5MM
	1x


2




A	M6x10
	4x
C	Ø18xØ6x1.5
	4x
D	5MM
	1x

II.

3



- B M6x20  
4x
  - C Ø18xØ6x1.5  
4x
  - D 5MM  
1x
- 80%



- D 5MM  
1x
- 100%



LE TRI  
+ FACILE



Séparez les éléments avant de trier