




NINA A 180




- 1** G40
- 2** G60o
- 3** G80W
- 4** D40S1
- 5** Worktop 40
- 6** D80Z
- 7** Worktop 80

NINA A G40








1x 4mm z1	8x Ø 6,3x50mm e27	8x Ø 12mm s3
8x Ø 8x30mm f1	2x Ø 35mm ab1	8x Ø 5mm d1
2x n165	1x L=128/148mm c252	5x 10x10x15mm l2
3x Ø 4,2x16mm p21	4x Ø 3,5x16mm p51	2x Ø 4x25mm p26
2x 80x27x5mm j1	4x Ø 4x30 mm p30	2x M4 r3









A	B (mm)			C	D
1	716	280	16	x1	1/7
2	716	280	16	x1	1/7
3	368	266	16	x1	1/7
4	368	280	16	x1	1/7
5	706	384	2.5	x1	1/7
6	367	250	16	x2	1/7
7	396	713	16	x1	6/7




1	n165 x 2 	p30 x 4 Ø 4x30mm	d1 x 8 Ø 5mm	b1 x 2 40x50x12mm	f1 x 8 Ø 8x30mm
----------	--------------	-------------------------	---------------------	--------------------------	------------------------









NINA A 180





- 1** G40
- 2** G60o
- 3** G80W
- 4** D40S1
- 5** Worktop 40
- 6** D80Z
- 7** Worktop 80


NINA A G60o



1x 4mm z1	8x Ø 6,3x50mm e27	8x Ø 12mm s3
8x Ø 8x30mm f1	2x Ø 35mm ab1	2x m5
2x n165	1x L=128/148mm c252	4x 10x10x15mm l2
4x Ø 4,2x16mm p21	4x Ø 3,5x16mm p51	2x Ø 4x25mm p26
2x 80x27x5mm j1	4x Ø 4x30 mm p30	2x M4 r3







A	B (mm)		C	D
1	358	280	16	x1 2/7
2	358	280	16	x1 2/7
3	568	266	16	x1 2/7
4	568	280	16	x1 2/7
5	582	348	2.5	x1 2/7
6	596	355	16	x1 6/7






7

j1 x 2
80x27x5mm





NINA A 180




- 1** G40
- 2** G60o
- 3** G80W
- 4** D40S1
- 5** Worktop 40
- 6** D80Z
- 7** Worktop 80

NINA A G80W







1x 4mm z1	12x Ø 6,3x50mm e27	12x Ø 12mm s3
12x Ø 8x30mm f1	2x Ø 35mm ab1	4x m5
2x n165	2x L=128/148mm c252	7x 10x10x15mm l2
16x Ø 4,2x16mm p21	8x Ø 3,5x16mm p51	4x Ø 4x25mm p26
2x 80x27x5mm j1	4x Ø 4x30 mm p30	2x M4 r3
		8x 10x6x10mm d6
		2x Ø 35mm ab2

A	B (mm)		C	D
1	716	280	16	x1 3/7
2	716	280	16	x1 3/7
3	768	266	16	x1 3/7
4	768	266	16	x1 3/7
5	768	280	16	x1 3/7
6	782	704	2,5	x1 3/7
7	796	355	16	x1 6/7
8	796	140	16	x1 6/7
9	764	192	4	x1 6/7
10	796	83	16	x1 6/7








1	n165 x 2 	p30 x 4 Ø 4x30mm 	b1 x 2 40x50x12mm 	f1 x 12 Ø 8x30mm 	m5 x 4 x2 	b2 x 2 40x50x12mm
----------	--------------	-------------------------	--------------------------	-------------------------	------------------	--------------------------






7

j1 x 2
80x27x5mm







NINA A 180



- 1** G40
- 2** G60o
- 3** G80W
- 4** D40S1
- 5** Worktop 40
- 6** D80Z
- 7** Worktop 80



NINA A D40S1




1x 4mm z1	8x Ø 6,3x50mm e27	8x Ø 12mm s3
8x Ø 8x30mm f1	2x Ø 35mm ab1	2x M4 r3
32x Ø 3x16mm p50	2x L=128/148mm c252	4x Ø 4x25mm p26
3x Ø 4,2x16mm p21	4x Ø 3,5x16mm p51	5x 10x10x15mm l2
4x Ø 4x30 mm p30	4x h=100mm k52	2x k61
	1x L=450mm n6	4x Ø 6x13mm e1





A	B (mm)		C	D
1	704	500	16	x1 4/7
2	704	500	16	x1 4/7
3	400	500	16	x1 4/7
4	367	80	16	x1 4/7
5	367	80	16	x1 4/7
6	382	710	2.5	x1 4/7
7	400	100	16	x1 4/7
8	366	470	16	x1 4/7
9	448	336	16	x1 4/7
10	336	71	16	x1 4/7
11	396	140	16	x1 6/7
12	396	570	16	x1 6/7











7




8



9







10








R



L




NINA A Worktop 40



A	B (mm)			C	D
1	400	600	28	x1	7/7





NINA A 180




- 1** G40
- 2** G60o
- 3** G80W
- 4** D40S1
- 5** Worktop 40
- 6** D80Z
- 7** Worktop 80

NINA A D80Z







1x 4mm z1	8x Ø 6,3x50mm e27	8x Ø 12mm s3
8x Ø 8x30mm f1	4x Ø 35mm ab1	2x M4 r3
20x Ø 3x16mm p50	2x L=128/148mm c252	4x Ø 4x25mm p26
16x Ø 4,2x16mm p21	8x Ø 3,5x16mm p51	2x k61
2x Ø 4x30 mm p30	4x h=100mm k52	2x L=75x25x15mm n14/2

A	B (mm)		C	D
1	704	500	16	x1 5/7
2	704	500	16	x1 5/7
3	767	80	16	x1 5/7
4	767	80	16	x1 5/7
5	800	500	16	x1 5/7
6	200	200	2,5	x1 5/7
7	800	100	16	x1 5/7
8	796	140	16	x1 5/7
9	396	570	16	x2 6/7







1	b1 x 4 40x50x12mm	f1 x 8 Ø 8x30mm	k62 x 2 	p50 x 4 Ø 3x16mm
----------	--------------------------	------------------------	-------------	-------------------------





NINA A Worktop 80



8x

 Ø 4,2x16mm **p21**

A	B (mm)			C	D
1	800	600	28	x1	7/7

1

p21 x 8


 Ø 4,2x16mm

