



NÁVOD NA MONTÁŽ HT-510



①



②




③




④




⑤



⑥



⑦



A×22




B×22




C×1




1




2




3




4




5




6




7



8



9



10

